


Industry : Mining & Metal
Machine: 24 Blower Blast Furnace No 5

40MW Combined axial / radial blast furnace blower. Major repairs to rotor and stator due to serious surge event resulting in blade damage and seal damage on compressor. A method of repair was decided on which involved grinding, re-profiling and machining the rotor blades and operating at reduced capacity due to increased blade clearance. The blower is back to successful operation.



MAN P Si Company Profile Workshop Applications

Authorised Service & Repair for:



MAN Turbo | PrimeServ

